

TECHNICAL INFORMATION




87961
February 2010

Subject ▶ Change of Striker and Cylinder 40

For Models ▶ HM1203C, HM1213C

Country ▶ All countries

Description ▶ For further improvement in hammering performance, Striker and Cylinder 40 have been modified as illustrated below.



Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
032	Striker 324991-4		1	Yes	Striker 326002-1		1	
036	Cylinder 40 331848-2		1	Yes	Cylinder 40 331925-0		1	

Implementation

To be implemented from March 2010 production