


TECHNICAL INFORMATION



A3877
February 2014

- Subject** ▶ Modification of M8 Set bolt
Elimination of Rubber cap
- For Models** ▶ RP0900, MT361, MRP090
- Country** ▶ All countries
- Description** ▶ To prevent the bolt from being removed,
 • M8 Set bolt has been modified as illustrated below.
 • Rubber cap has been eliminated.



Interchangeability(I/C)

Item No.	Current part	Q'ty	I/C	New part	Q'ty	Note
035	M8 Set bolt 266460-8	1	No	M8 Set bolt 266920-0	1	Interchangeable as a set
004	Rubber cap 424156-9	1				

Implementation

RP0900, MRP090 for Central and South American countries: From March 2014 production
 RP0900, MRP090 for all countries except above: After the current parts in stock are cleared.
 MT361: After the current parts in stock are cleared.