

TECHNICAL INFORMATION



86673


November 2009

Subject ▶ Change of Spindle and Compression Spring 45,
Addition of Compression Spring 49 and Flat Washer 35

For Models ▶ TW1000

Country ▶ Argentina, Austria, Bhutan, Brazil, Chile, China, Columbia, Cyprus, France, Germany, Hong Kong, India, Indonesia, Italy, Kuwait, Mexico, Netherlands, Panama, Philippines, Poland, Reunion, Russia, Saudi Arabia, South Africa, Spain, Sweden, Switzerland, Tahiti, Taiwan, Thailand, Turkey, UK, USA, Vietnam

Description ▶ The components of Spindle section have been changed/ added as illustrated below for further improvement in durability of Hammer.



Interchangeability(I/C)

Item No.	Current part	Q'ty	I/C	New part	Q'ty	Note
013	Spindle ----- 324501-7	1	No	Spindle ----- 324666-5	1	The current parts remain available. Interchangeable as a set
010	Compression Spring 45 ----- 233428-9	1	No	Compression Spring 36 ----- 231211-8	1	
058	-----			Compression Spring 49 ----- 231212-6	1	
059	-----			Flat Washer 35 ----- 253713-4	1	

Implementation

From serial No. 24530E (October 2009)