

CHNICAL INFORMATION

Tnakita

99132

(Page 1 of 3) September 2014

Subject

► Modification of Controller

For Models | HM1214C, HM1307C, HM1307CB, HM1317C, HM1317CB


Country

All countries

Description

Material of Controller case has been changed for further improvement in the durability. Both side adhesive tape and two Plates (Re: our previous Technical information No. 91793) have been eliminated.

Thickness of screw fastening portions of Controller case has been changed from 3 mm to 4.5 mm, and therefore, M4x16 Hex socket head bolts have been replaced with M4x18 Hex socket head bolts.



Interchangeability(I/C)

Item No.	Current part	Q't	y I/C	New part	Q'ty	Note
132	Controller assembly 141803-4	1				HM1214C for Brazil, Canada, Colombia, Guam, Mexico, Panama, Saudi Arabia, UK, USA
107	Controller (with mark of "Low 110- 130V") 620151-9	1	No	Controller (with mark of "Low 110- 130V") 620225-6	1	
131	Both side adhesive tape 442180-0	1				
130	Plate 346546-5	2				
108	Hex socket head bolt M4x16 265490-6	2	No	Hex socket head bolt M4x18 with GM 266834-3	2	
132	Controller assembly 141804-2	1				Interchangeable as a set HM1214C for Argentina, Australia, Austria, Bhutan, Brazil, Chile, Cyprus, France, Germany, India, Indonesia, Italy, Malaysia, Netherlands, New Zealand, Philippines, Poland, Reunion, Russia, Saudi Arabia, Singapore, South Africa, Spain, Sweden, Switzerland, Thailand, Turkey, UK, Vietnam
107	Controller (with mark of "High 220- 240V")	1	No	Controller (with mark of "High 220- 240V") 620226-4	1	
131	Both side adhesive tape 442180-0	1				
130	Plate 346546-5	2				
108	Hex socket head bolt M4x16 265490-6	2	No	Hex socket head bolt M4x18 with GM 266834-3	2	
122	Controller assembly 141801-8	1				HM1307C and HM1307CB for Brazil, Colombia, Guam, Mexico, Panama, Saudi Arabia, USA
107	Controller (with mark of "Low") 631916-4	1	No	Controller (with mark of "Low") 620227-2	1	
121	Both side adhesive tape 442180-0	1				
080	Plate 346546-5	2				
108	Hex socket head bolt M4x16	2	No	Hex socket head bolt M4x18 with GM 266834-3	2	
122	Controller assembly 141802-6	1		2000313		Interchangeable as a set HM1307C and HM1307CB for Argentina, Australia, Austria, Austria, Bhutan, Brazil, Chile, China, Commonwealth of Dominica, Cyprus, France, Hong Kong, Iran, Korea, Kuwait, Netherlands, Poland, Reunion, Russia, Saudi Arabia, South Africa, Spain, Thailand, Turkey, Vietnam
107	Controller (with mark of "High") 631917-2	1	No	Controller (with mark of "High") 620228-0	1	
121	Both side adhesive tape 442180-0	1				
080	Plate 346546-5	2				
108	Hex socket head bolt M4x16 265490-6	2	No	Hex socket head bolt M4x18 with GM 266834-3	2	

Interchangeability(I/C)

Item No.	Current part	Q'ty	I/C	New part		Q'ty	Note
122	Controller assembly 141799-9	1					
107	Controller (with mark of "Low 100- 130V")	1	No	Controller (with mark of "Low 100- 130V")		1	HM1317C and HM1317CB for Brazil, Canada, Colombia, Guam, Hong Kong, Mexico, Panama, Saudi Arabia, Taiwan, UK, USA
	631919-8			620229-8			
121	Both side adhesive tape	1					
	442180-0						
080	Plate	2					
	346546-5						
108	Hex socket head bolt M4x16	2	No	Hex socket head bolt M4x18 with GM		2	
	265490-6			266834-3			
122	Controller assembly 141800-0	1					HM1317C and HM1317CB for Argentina, Australia, Austria, Brazil, Chile, China, Cyprus, France, Germany,
107	Controller (with mark of "High 220- 240V")	1	No	Controller (with mark of "High 220- 240V")		1	
	631920-3			620230-3			
121	Both side adhesive tape	1					Hong Kong, Indonesia, Iran,
	442180-0						Italy, Korea, Malaysia, Netherlands, New Zealand,
080	Plate	2					Philippines, Poland, Reunion, Russia, Saudi Arabia, Singapore, South Africa, Spain, Sweden, Switzerland, Turkey, Vietnam
	346546-5						
108	Hex socket head bolt M4x16	2	No	Hex socket head bolt M4x18 with GM		2	
	265490-6			266834-3			

Implementation

HM1214C: March 2013 production HM1307C: January 2013 production HM1307CB: December 2012 production HM1317C: December 2012 production HM1317CB: December 2012 production